



# DB11

## Recess Mounted Safety Beam

## INSTALLATION INSTRUCTIONS

If arcing occurs between the door frame and the DB11 chassis, it is an indication that one side of the secondary of the transformer is grounded. This may occur intentionally or inadvertently through other devices connected to the same transformer. The voltage difference may be measured as shown in the diagram.

To assure proper operation of the DB11 beam set, reverse the power connections to both the DB11 transmitter and receiver. When connected correctly, no voltage will be measured.

The diagram depicts both connection methods.

